



Current Version

[[V5.40.008](#)]

View Older Versions

[[V5.40.008](#)] [[V5.20.000](#)] [[V5.18.001](#)] [[V5.16.000](#)] [[V5.14.000](#)] [[V5.12.000](#)] [[V5.10.015](#)]
[[V4.96.001](#)]

V5.40.008(released on October 31, 2019)

Firmware Download

[V5.40.008](#)

Manuals

[Go to "All Manual"](#)

What's New

- Added AC fail and AC restore events to be reported in 10 seconds to be compliant with EN-50131.
- Added serial lockout for 24hours after 20 invalid codes; it can be unlocked by arming and disarming from the keypad with the master code.
- Added WD1 support

V5.23.000(released on May 25, 2018)

Firmware Download

[SP4000 V5.23.000](#)

What's New

- Fix a bug that caused the panel to show a wrong time.

V5.20.000(released on April 13, 2016)

Firmware Download

[SP4000 V5.20.000](#)

Improvements

- Generate a 2100Hz tone at the beginning of a modem connection to improve the modem communication on VOIP lines